

Menu

HISTORY FILE MAP for year 2003

REALTIME


PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

281.08:32-08:49 18m 1024bps realtime data and 36m
(281.00:26-01:02) 512bps playback data lost due to
downlink control channel processor
failure at DSS65. DR M101961 refers.

281.16:45-17:10 45m 1024bps realtime data and 50m 512bps playback
281.16:25-16:45 512bps playback data lost due to Uninterruptible Power
(281.15:35-16:25) Supply failure at DSS25 causing a delay in the station
coming online. DR G103463 refers.



Data still onboard DSU